




Option M1...the amplifier is equipped with a 3.5 digit panel meter to display sensor output voltage. Full bandwidth analog voltage is available as usual on the barrier strip output terminal.

Option M2...the amplifier is equipped with a 3.5 digit panel meter to display displacement.

The meter can be scaled for inch or metric units. For D models, the user must specify scaling for the near side or the far side (scaling for both is not available). Meter readings are accurate within the bounds of the sensor's linear range as defined on the calibration chart.

With M2, the amplifier is also equipped with a zero adjust control.